

NICHOLS CLEANING RECOMMENDATIONS

FABRIC: SPOT CLEANING

Wet Cleaning Method

We recommend using water with a mild detergent for spot cleaning all our fabrics, except Celtic Cloth.

We have found the following products to be effective:

- Resolve Carpet Cleaner
- Goof Off 2
- Krud Kutter

Caution: Celtic Cloth may spot when cleaning regardless of substance used including water. Test wet cleaning first in a non-critical area.

Dry Cleaning Method

- Rub area with a white art eraser such as 'Staedtler Mars Plastic'.
- Brush area with a small firm nylon Brush.
- Use compressed air to remove statically attracted dust.

FABRIC: FULL CLEANING

Only wash fabrics in cold water. When drying use air only no heat and don't completely dry in a dryer. In order to finish drying process allow to air dry. (For structures, fabric pop ups or banner stands place fabric cover on the frame to finish drying.)

FABRIC: LAUNDRY SERVICE

Many laundry/dry cleaning businesses offer drop off service. Ask for a cold water wash and air only drying (no heat).

*****Heat may cause shrinkage especially on products with a fabric liner *****

ALUMINUM: SPOT CLEANING

Over time the bent portions of aluminum framing may develop a frosty appearance. To reduce the appearance of these marks, use the following methods:

Wet Cloth Method

- Soak a soft, non-abrasive cloth in warm, sudsy water.
- Rub cloth sideways against the grain of the aluminum.
- Dry immediately with a soft, non-abrasive cloth.

Lotion Method

The lotion method is recommended for tougher, more stubborn marks and is most effective when preceded by the wet cloth method.

- Thoroughly cover affected area with a gentle, scent-free lotion.
- Rub into aluminum sideways against the grain.
- Spot clean excess lotion with a soft, non-abrasive cloth.
- Allow to air dry.

GENERAL CARE: PACKING AND STORAGE

- Always handle fabric and booth components with care.
- Wash your hands before handling the booth and handle in a clean, protected environment; use the white gloves and drop cloth provided with your booth whenever possible.
- Inspect fabric for visible dirt or stains before packing and cleaning.
- Be sure to allow time for drying before packing if wet cleaning methods are used.
- Turn fabric inside out before packing.
- Always use original shipping components (bags, boxes, protective coverings, etc.) when packing and storing booth pieces.
- Store booth in a cool, dry environment (45° to 75°F), preferably one with controlled levels of temperature and humidity.

Note: The above are only recommendations. We offer no guarantee and will not replace damaged products.